

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Figure 2: Continuous monitoring of a seal by observing the control pressure, in this case, by way of example, by means of two pressure switches



PHB71676




Figure 3: Monitoring of a seal by observing the control pressure, venting from time to time via a pressure relief valve with hysteresis



PHB71676




Figure 4: Monitoring of a seal by observing the control pressure, venting from time to time via a 2/2-way switching valve of the "normally closed" type, driving for example by means of two-position pressure switch



PHB71676




Figure 5: Monitoring of a seal by observing the control pressure, venting from time to time via a 2/2-way switching valve of the "normally closed" type, driving via evaluation unit